

March 2025 Construction Update

RERAA KM 46 OF 2022-2023





Structural Work

- 1st to 14th floor (Terrace) roof slab casted
- Mumty, OHWT, Pergola casted

Plastering Work

- 1st to 14th floor internal plaster completed
- External Plaster in Progress (95% done)

Plumbing Work

- 1st to 14th floor plumbing concealed work completed
- Vertical Sewage, Soil, Rainwater, Kitchen & Balcony outlet & Water line in progress (90% done)
- Horizontal Sewage Soil line of Bathroom down slab in progress (90% done)

Masonry Work

■ 1st to 14th floor AAC Block masonry completed

Electrical Work

■ 1st to 14th floor electrical pipe concealed work completed

Waterproofing Work

■ 1st to 14th floor down slab waterproofing completed

Internal Wall Putty Work

1st to 14th floor internal wall putty in Progress Tiles Work

- 4th to 14th floor, Floor Tiles fitting in Progress
- 4th to 8th floor, Bathroom Tiles fitting in Progress
- 4th to 8th floor, Kitchen Granite top installation in Progress





Structural Work

- 1st to 14th floor (Terrace) roof slab casted
- Mumty, OHWT, Pergola casted

Plastering Work

- 1st to 14th floor internal plaster completed
- External Plaster in Progress (95% done)

Plumbing Work

- 1st to 14th floor plumbing concealed work completed
- Vertical Sewage, Soil, Rainwater, Kitchen & Balcony outlet & Water line in progress (95% done)
- Horizontal Sewage Soil line of Bathroom down slab in progress (90% done)
- Water Distribution Ring work in progress (90% done)
- Sewage Line work in progress

Masonry Work

■ 1st to 14th floor AAC Block masonry completed

Electrical Work

■ 1st to 14th floor electrical pipe concealed work completed

Waterproofing Work

■ 1st to 14th floor down slab waterproofing completed

Internal Wall Putty Work

1st to 14th floor internal wall putty in Progress

Tiles Work

- 3rd to 12th floor Tiles fitting in Progress
- 3rd to 10th floor Bathroom Tiles fitting in Progress
- 3rd to 9th floor Kitchen Granite top installation in Progress





Structural Work

- 1st to 14th floor (Terrace) roof slab casted
- Mumty, OHWT, Pergola casted

Plastering Work

- 1st to 14th floor internal plaster completed
- External Plaster in Progress (95% done)

Plumbing Work

- 1st to 14th floor plumbing concealed work completed
- Vertical Sewage, Soil, Rainwater, Kitchen & Balcony outlet & Water line in progress (95% done)
- Horizontal Sewage Soil line of Bathroom down slab in progress (90% done)
- Water Distribution Ring work in progress (90%)
- Sewage Line work in progress

Masonry Work

■ 1st to 14th floor AAC Block masonry completed

Electrical Work

1st to 14th floor electrical pipe concealed work completed

Waterproofing Work

■ 1st to 14th floor down slab Waterproofing work completed

Internal Wall Putty Work

1st to 14th floor internal wall putty in Progress

Tiles Work

- 2nd to 14th floor Tiles fitting in Progress
- 3rd to 14th floor Bathroom Tiles fitting in Progress
- 2nd to 10th floor Kitchen Granite top installation in Progress





Structural Work

- 1st to 14th floor (Terrace) roof slab casted
- Mumty, OHWT, Pergola casted

Plastering Work

- 1st to 14th floor internal plaster completed
- External Plaster in Progress (95% done)

Plumbing Work

- 1st to 14th floor plumbing concealed work completed
- Vertical Sewage, Soil, Rainwater, Kitchen & Balcony outlet & Water line in progress (95% done)
- Horizontal Sewage Soil line of Bathroom down slab in progress (90% done)
- Water Distribution Ring work in progress (90%)
- Sewage Line work in progress

Masonry Work

■ 1st to 14th floor AAC Block masonry completed

Electrical Work

1st to 14th floor electrical pipe concealed work completed

Waterproofing Work

■ 1st to 14th floor down slab Waterproofing work completed

Internal Wall Putty Work

1st to 14th floor internal wall putty in Progress


Tiles Work

- 2nd to 13th floor, Tiles fitting in progress
- 3rd to 13th floor Bathroom Tiles fitting in progress
- 2nd to 13th floor, Kitchen Granite top installation in progress









Structural Work

- 1st to 14th floor (Terrace) roof slab casted
- Mumty, OHWT, Pergola casted

Plastering Work

- 1st to 13th floor internal plaster completed
- External Plaster in Progress (90% done)

Plumbing Work

- 1st to 14th floor plumbing concealed work completed
- Vertical Sewage, Soil, Rainwater, Kitchen & Balcony outlet & Water line in progress (80% done)
- Horizontal Sewage Soil line of Bathroom down slab in progress (65% done)

Masonry Work

■ 1st to 14th floor AAC Block masonry completed

Electrical Work

■ 1st to 14th floor electrical pipe concealed work completed

Waterproofing Work

■ 1st to 14th floor down slab waterproofing in progress

Internal Wall Putty Work

1st to 14th floor internal wall putty in progress

Tiles Work

3rd to 5th floor tiles fitting in progress





